The New York Landmarks Conservancy Lucy G. Moses Preservation Awards Submittal




New York City Police Museum 100 Old Slip New York, New York

Exterior Renovation



32 Avenue of the Americas New York, NY 10013 Tel 212 505 1133 www.superstructures.com



January 12, 2012

Lucy G. Moses Preservation Awards The New York Landmarks Conservancy One Whitehall Street New York, NY 10004

Re: New York City Police Museum 100 Old Slip, New York, NY

Dear Sir / Madam:

SUPERSTRUCTURES: Engineering + Architecture, PLLC takes great pleasure in nominating the New York City Police Museum for your consideration as a worthy recipient of a Lucy G. Moses Preservation Award. Having been designated a New York City Landmark, the building has long been recognized as a "striking example of municipal architecture," in the words of the Landmarks Preservation Commission.

The museum housed in this landmark serves an important public function as an accessible public resource. Through its exhibitions, collections and education programming, the New York City Police Museum illustrates how the policies and culture of the NYPD have evolved time to meet the changing needs of the City. It is certainly fitting that its current home was built over 100 years ago as a home for the NYPD's First Precinct.

The recently completed exterior restoration was necessitated in large part by an inappropriately detailed addition on the fifth floor, resulting in improper drainage from the roof, and subsequent leakage on interior floors and staining of the exterior limestone. This problem was solved, as is detailed in the following pages along with the other elements of a restoration project which protected this very worthy edifice beginning its second century of service.

Our thanks to the Conservancy for the opportunity to present this estimable historic building as a candidate for consideration for a Lucy G. Moses Preservation Award.

Very truly yours,

SUPERSTRUCTURES

Engineering + Architecture, PLLC

Paul Millman, PE, RA, LEED AP

Principal



First Precinct circa 1910.

First Precinct Police Station / New York City Police Museum

The First Precinct Police Station, which now houses the New York City Police Museum, is an impressive public building and important civic institution which, though erected in 1909, still commands its waterfront site. As home of the Landmarks Preservation Commission in the 1990s, the building had become a symbol of the City's commitment to historic preservation.

In awarding the building Landmark status in 1977, the Landmarks Preservation Commission cited the building's "special character, special historical and aesthetic interest and value as part of the development ...of New York City" and further recognized that "in its massive scale and restrained ornamentation the building creates an imposing effect."

The station house stands on Old Slip, in an area which has been important to the city since the late 17th century. Old Slip, at the foot of William Street, was the first slip in the city. These slips were openings between two wharves where boats unloaded during high tide. Old Slip became the site of one of the first official market places in New Amsterdam, reaching the peak of its popularity in the 1720s. Beginning in the late 18th century, the Slip began to be filled in and eventually it formed a wide street of the same name.



The First Police Precinct in New York City was originally housed in the Franklin Market on Old Slip, when the department was organized in 1844. It wasn't until 1884 that the First Precinct Station got its own building at Old Slip. This was a four story structure which stood until the present station house was erected on the same site in 1909-1911.

Renderings of this new station house were displayed at the 23rd Annual Exhibit of the Architectural League of New York in 1908. The architects, Richard Howland Hunt (1862-1931) and Joseph Howland Hunt (1870-1924), were well known for their elegant Long Island and Newport residential works, as well as for their New York City town houses. They designed the George Washington Vanderbilt House (1902-1905), also a designated New York City Landmark. Richard Howland Hunt also carried out his father Richard Morris Hunt's design for the central portion of the Metropolitan Museum of Art after his death.

The First Precinct Police Station remains a striking example of municipal architecture. This handsome neo-Italian Renaissance building of limestone is divided horizontally into three sections — a low base, a rusticated center section, and a smooth-faced "attic" story. Its visual power is created by the rhythmic series of tall arches, heavy walls and restrained ornamentation. The police station has the distinctive profile of an early Italian Renaissance palazzo. Many of the features, such as the arched openings of the main story, the rustication of the center section, and the dominating cornice, are reminiscent of the fifteenth century Palazzo Riccardi in Florence, designed by Michelozzo.


All four faces of this freestanding building are treated in a generally similar manner. A molded granite base supports the pulvinated rustication of the center section. Above the low base, a series of round-arched openings, serving two stories, have smooth-faced enframements and bracketed sills at the windows. The third story fenestration consists of small square paired windows separated by mullions. Just above these attic windows, a handsome roof cornice with console brackets above a row of dentils elegantly crowns this fine building. In the 1980s, a fifth story was added --- largely obscured from street level by the cornice, it was capped with a Spanish-clay-tile roof.

This police station was occupied by the First Precinct until January 1973. It is therefore fitting that the building is currently occupied by the New York City Police Museum, celebrating the history and contributions of the New York City Police Department. The museum, which grew from a gallery housed at the police academy on 20th Street, opened in 2000, and moved to its current location at 100 Old Slip in January 2002. Museum officials saw a move to this location as an opportunity to connect with the Department's history. The museum gives visitors an insider's look at the history and traditions of the largest police service in the country. Among its exhibits are a display of the evolution of police uniforms since their inception in 1853, the first machine gun used in a gangland killing in New York, a model of a jail cell, a timeline of transportation, and a Hall of Heroes that includes the name and badge of every NYPD officer killed in the line of duty, starting with David Martin on August 6. 1861.

The renovation project done under the auspices of New York City's Department of Design and Construction and completed in 2011 included new and refurbished windows throughout the building, reconstruction of the water-shedding system at the fifth floor to eliminate water infiltration, and restoration of exterior masonry and metalwork as needed to bring the building into watertight and restored condition. Captions accompanying the photos on subsequent pages highlight some of the challenges and achievements of the project.

In its combination of architectural distinction, historical import and civic utility the Police Museum is a treasure well worth preserving and the recent restoration allows it to shine in a manner befitting its pedigree.





SOUTH ELEVATION

RESTORATION SCHEDULE:

ID CODE	RESTORATION ITEM	SYMBOL	UNIT	DWG.
CLN 01	LIMESTONE MASONRY	N/A	SF	A203/A301
CLN 02	LIMESTONE MASONRY WITH BIOCIDE		SF	A301
CLN 03	REMOVAL OF ADHESIVE RESIDUE	N/A	SF	A301
CLN 04	GRANITIC GNEISS MASONRY		SF	A301
JNT 01	JOINT SEALANT REPLACEMENT	N/A	LF	A301
MTL 01	LIGHT FIXTURE REINSTALLATION	N/A	EA	A304
MTL 02	SHEET METAL CRESTING INSTALLATION	N/A	LF	A406
PNT 01	STONE MASONRY POINTING	N/A	LF	A301

ID CODE	RESTORATION ITEM	SYMBOL	UNIT	DWG.
SHM 01	FLAT SEAM METAL ROOFING	N/A	SF	A405
STN 01	LIMESTONE CRACK REPAIR	\{	LI	A301
STN 02	STONE DUTCHMAN REPAIR		CF	A302
STN 03	STONE CRACK REPAIR AT LIMESTONE SILL	ş	LF	A302
STN 04	STONE UNIT REPLACEMENT		EA	A303
STN 05	RESETTING OF JACK ARCH UNIT		EA	A303
STN 06	STONE REPAIR AT FRONT ENTRANCE	N/A	SF	A304
STN 07	STONE PATCH REPAIR	N/A	SI	A304


SYMBOLS:

A.C. — LOCATION FOR REINSTALLATION OF EXISTING WINDOW AIR CONDITIONING UNIT UPON COMPLETION OF WINDOW REPLACEMENT.

- LOCATION OF EXISTING LOUVERS TO BE REPLACED

NOTES:


- 1. ALL EXISTING WROUGHT IRON WINDOW GRILLES TO BE SCRAPED, PRIMED AND REPAINTED PER SPECIFICATION SECTION 099700.
 2. ALL EXISTING CAST IRON WINDOW SPANDREL PANELS TO BE SCRAPED, PRIMED AND REPAINTED PER SPECIFICATION SECTION 099700.
 3. SURFACE MOUNTED METAL ANCHORS THROUGHOUT FACADES TO BE REMOVED FROM STONE AND PATCHED WITH REPAIR MORTAR PER SPECIFICATION SECTION 040140.
 4. REMOVE EXISTING LOUVERS AND PROVIDE NEW TO MATCH EXISTING
- DIMENSIONS AND PER SPECIFICATION SECTION 089100. PROVIDE WALL MOUNTED LOUVER FLASHING DETAILS PER STU 01/A404.





Masonry / Limestone

Despite their age, the limestone walls of the building were in good condition, though there was some staining from the water infiltration off the fifthfloor roof, atmospheric soiling and biological growth. Most of the masonry work comprised pointing and cleaning to restore the limestone to its original appearance, some stone restoration work including Dutchmen, unit replacement and crack repair. Landmarks Preservation Commission approval of mortar selection was required. During the renovation the scaffolding subcontractor was able to utilize a tension system inside the masonry window openings to stabilize the scaffolding. This unusual approach meant that no holes were required in the existing stone to anchor the scaffolding.













Windows

Prior to this project, the window sashes had been replaced within the original frames. The existing windows had problems with operation and with air and water infiltration. SUPERSTRUCTURES kept all the existing original wood frames in place, restoring the wood, and designed new, insulated glass replacement sashes to fit each opening. A paint analysis was done on the original frames, cast iron spandrel panels, and wrought iron grilles in order to match the original historic colors.

Top, left: Window and wrought iron grille before restoration. Bottom, left and right: Windows during restoration. Top, right: Windows, spandrel panels and grilles after restoration.










Fifth Floor

The major challenge of the restoration related to the fifth floor of the building, itself an addition done in the 1980s. The addition was positioned on top of the existing parapets, from which a copper cresting had prevoiusly been removed. No piece of the original cresting survived. The fifth floor tile roof drained onto a gutter on the parapet which was in poor condition, resulting in leakage into the interior floors below and causing staining and displacement of arch stones on the exterior. A new copper cresting to go atop the parapet was designed based on one historic photo including the original cresting and research of pressed-metal catalogs of the era. Clay mock-ups were made and were reviewed before molds were created for the copper stamping.













Fifth Floor - continued


Behind the new cresting, a "gutter" was created out of the back of the cresting, the existing pitch of the coping stone and built-up cement board to provide positive pitch to drain the run-off from the roof. Scuppers were relocated and one drain line added to allow for easier maintenance. Also the windows at the fifth floor, originally double-hung configuration, were replaced with casement windows, that better match the style of the historic windows below and allow easier access through the windows onto the reverse dormer roofs for maintenance of the new drains and scuppers.


Top, left: Reverse dormer window before replacement. Bottom, left: Copper cresting during installation on parapet. Bottom, right: New window leaning against old window, prior to replacement. Top, right: New casement window installed.




















2011 Nomination Form

Name of Proj	ect: New York City Police Museum
Address or Pro	ject Location: 100 Old Slip at South Street
Property Owr	ner: New York City Department of Cultural Affairs
Contact Persor	/Title: Betsy McClelland
	Chambers Street, Second Floor, New York, NY 10007 v, State and Zip Code)
Project done u	212) 513-9336 Email: <u>bmcclelland@culture.nyc.gov</u> Inder auspices of NYC Dept. of Design and Construction, Michael Nastasi, (718) 391-1174 **rmation* (if known)
Date of Constr	uction: 1909-11 Original Architect: Hunt & Hunt
Landmark statu	us of property (check all that apply):
Ne Ind Sta	ividual New York City landmark w York City Historic District/Name of District ividually listed on the State and National Register and National Register Historic District/ Name of District:
Project start da	ate: April 2008 Completion date: December 2011
Approximate B	udget: \$3 Million Include list of any governmental programs that provided financial assistance in narrative.
Nominated by	y: Paul Millman, PE, RA
Title/Company	Principal, Superstructures Engineering + Architecture, PLLC
	Avenue of the Americas, New York, NY 10013 v, State and Zip Code)
Telephone: (2	12) 505-1133 Email: pmillman@superstructures.con
	ultants, Architects, Engineers, Contractors, Designers Use additional pages if necessary):
Company: S	uperstructures Engineering + Architecture, PLLC
Name/Title: _	Paul Millman, PE, RA - Principal
Address: 32	Avenue of the Americas, New York, NY 10013
(Street address, City	v, State and Zip Code)
Telephone: (2	212) 505-1133 Email: _pmillman@superstructures.con

2011 Nomination Form

	onsultants, Architects, Engineers, Contractial. Use additional pages if necessary):	tors, Des	igners			
Company:	BQE Industries, Inc. (Contractor)					
Name/Title	Mike Mashraqui, Project Manager					
, taar 000	40-49 72nd Street, Woodside, NY 11377	•				
Telephone:	(718) 429-1648	Email:	bqeindustries@yahoo.com			
Company:	ny:Ceprine Scaffolding Services (Sidewalk Bridge and Scaffolding)					
Name/Title	Ivan Cerina, Owner					
, taar 000	41-08 Berrian Boulevard, Astoria, NY c, City, State and Zip Code)					
Telephone:	(718) 728-4848	Email:	info@ceprinescaffolding.com			
Company:	Xaren Corporation (Asbestos and Lead	d Abatem	ent)			
Name/Title	Akinyemi Babatunde, President					
Address: _	45-09 Green Point Avenue, Long Island	City, NY	11104			
(Street address	s, City, State and Zip Code)					
Telephone:	(718) 729-3939	Email:	N/A			
Company:	Company: Zone Plumbing & Heating Corp. (Plumbing)					
Name/Title	Leslie Lynch					
Address: _	1092 Dekalb Avenue, Brooklyn, NY 112	21				
(Street address	s, City, State and Zip Code)					
Telephone:	(718) 452-3182	Email:	zoneplumbheat@gmail.com			
Company:	Cordial Construction Inc. (Wood Window	w Installa	tion/Repair)			
Name/Title	Paramjeet Singh, President					
_	58-14 32nd Avenue, Woodside, NY 1137 a, City, State and Zip Code)	77				
Telephone:	(718) 989-4334	Email:	cordialconstructioninc@yahoo.com			

2011 Nomination Form

	all. Use additional pages if necessary):	ctors, De	signers
Company:	Custom Wood Reproductions Inc. (Woo	od Windo	ow Sashes, New Casement Windows)
Name/Title	Jane Elletson, President		
	115 Servistar Industrial Way, Westfield, s, City, State and Zip Code)	MA 0108	35
Telephone:	(413) 562-8900	Email:	info@customwoodreproductions.com
Company:	Michigan Ornamental Metals (Copper C	Cresting	- Stamps)
Name/Title	Mike Radigan, Division Manager		
, laar 000.	1033 Slocum Avenue, Ridgefield, NJ 076	657	
Telephone:	(201) 945-4930	Email:	michaelra@michiganornamental.com
Company:	B & B Sheet Metal, Inc. (Copper Crestin	ng - Asse	embly)
Name/Title	Robert Baschnagel		
, taar 000.	2540 50th Avenue, Long Island City, NY s, City, State and Zip Code)	11101	
	(718) 433-2501	Email:	bbsheetmetal@aol.com
Company:	Pasvalco (Limestone)		
Name/Title	George Heckel, CEO		
Address:	100 Bogert Street, Closter, NJ 07624		
	(201) 768-2133	Email:	george@pasvalco.com
Company:	Gladding, McBean LLC (Tile)		
Name/Title	Lynn Haines, Architectural Sales		
Address:	601 7th Street, Lincoln, CA 95648		
	s, City, State and Zip Code)		
Telephone:	(916) 644-9304	Email:	lynn.haines@paccoast.com

2011 Nomination Form

Project Consultants, Architects, Engineers, Contractors, Designers (Please list all. Use additional pages if necessary):				
Company: Siplast, Inc. (Liquid Applied Roofing))			
Name/Title: _Jim Mollenhoff, President				
Address: 1000 E. Rochelle Boulevard, Irving, T (Street address, City, State and Zip Code)	TX 75062			
Telephone: 469-995-2200	Email: usinfo@icopal.com			
Company:Burns Engineering, Inc.				
Name/Title: Ben Gidwani, PE				
Address: 11 Penn Center 1835 Market Street, (Street address, City, State and Zip Code)	, Suite 300, Philadelphia, PA 19103			
Telephone:(215) 979-7703	Email: bgidwani@burns-group.com			
Company:				
Name/Title:				
Address:				
(Street address, City, State and Zip Code)				
Telephone:	Email:			
Company:				
Name/Title:				
Address:				
Telephone:	Email:			
Company:				
Name/Title:				
Telephone:	Email:			