FAÇADE REPAIRS															
Description		Unit Cost (\$)		Priority 1											
				Priority 1 / C 1			Priority 1 / C2			Priority 2			Priority 3		
	Unit	(\$) low	(\$) high	Quantity	(\$) low	(\$) high	Quantity	(\$) low	(\$) high	Quantity	(\$) low	(\$) high	Quantity	(\$) low	(\$) high
Site Protection		(.,,	· · · · · · · · ·	,	(1)	(1)	,	(1)	(1)	,	(1)	(1)	,	(1)	(1)
Sidewalk shed (standard 10' wide with wood catchalls &															
incandescent lights)	lf	\$75.00	\$100.00	600	\$45,000	\$60,000				450	\$33,750	\$45,000	600	\$45,000	\$60,000
Suspended Scaffolds & Rigging	ea	\$2,000.00	\$3,000.00	28	\$56,000	\$84,000	Inclu	uded in Priority 1	1/1	24	\$48,000	\$72,000	28	\$56,000	\$84,000
Pipe Scaffolds	lf	\$3.50	\$4.50	12,000	\$42,000	\$54,000				12,000	\$42,000	\$54,000	12,000	\$42,000	\$54,000
Roof protection 1/2" plywood layout	sf	\$2.00	\$3.00	6,000	\$12,000	\$18,000				5,000	\$10,000	\$15,000	6,000	\$12,000	\$18,000
Façade Repairs															
COA 01: Coating of soffit shelf angle	lf	\$7.50	\$10.00										590	\$4,425	\$5,900
COA 02: Coating of window steel lintel	lf	\$7.00	\$9.50										2,805	\$19,635	\$26,648
CON 01: Cracked / spalled concrete repair (at column)	si	\$2.00	\$2.50	300	\$600	\$750							,	. ,	,.
CON 02: Spalled concrete repair (at cooling tower courtyard															
beams and columns)	si	\$1.50	\$2.00							10,000	\$15,000	\$20,000			
CON 03: Concrete repair around embedded rail posts	ea	\$200.00	\$250.00										2	\$400	\$500
COP 01: Coping stone replacement	ea	\$500.00	\$550.00				5	\$2,500	\$2,750						
COP 02: Coping stone repair	ea	\$200.00	\$250.00										2	\$400	\$500
COR 01: Brick masonry corner repair	vlf	\$180.00	\$225.00	23	\$4,140	\$5,175									
COR 02: Brick masonry corner repair (at 120° to 90° corner	ea	\$2,000.00	\$2,250.00	8	\$16,000	\$18,000									
CLN 01: Removal of biological grows from face brick masonry	sf	\$3.50	\$4.00										750	\$2,625	\$3,000
GLA 01: Light fixture repair	ea	\$100.00	\$110.00										3	\$300	\$330
GLA 02 : Window glass installation	ea	\$120.00	\$140.00							1	\$120	\$140			
* JNT 01: Sealant replacement at soffit angle	lf	\$7.50	\$9.00	30	\$225	\$270							580	\$4,350	\$5,220
* JNT 02: Sealant replacement between and below coping stone								.							
units	lf ''	\$9.00	\$10.50				3,975	\$35,775	\$41,738	110	A== 0	4005	280	\$2,520	\$2,940
* JNT 03: Window perimeter caulking replacement	lf	\$7.00	\$8.50							110	\$770	\$935	3,590	\$25,130	\$30,515
* JNT 04: Sealant replacement at building expansion / control															
joints	lf	\$7.50	\$9.00										2,885	\$21,638	\$25,965
* JNT 05: Sealant replacement at plaster ceiling joints	lf ,	\$7.50	\$9.00		01.015	* 4 * 5 0 0	0.1	A		4	4000	4000	235	\$1,763	\$2,115
MAS 01: Cracked masonry repair	sf	\$55.00	\$80.00	19	\$1,045	\$1,520	31	\$1,705	\$2,480	4	\$220	\$320		# 400	# 400
MAS 02: Replacement of cracked / spalled bricks	sf	\$65.00	\$90.00	34	\$2,210	\$3,060	84	\$5,460	\$7,560	100	\$6,500	\$9,000	2	\$130	\$180
PLS 01: Plaster ceiling repair	sf	\$30.00	\$35.00 \$9.00	C40	¢4.400	ФГ 7 00				2,200	\$66,000	\$77,000	00	\$560	\$720
PNT 01: Weathered joint pointing PNT 02: Counterflashing joint pointing	II II	\$7.00 \$11.00	\$9.00 \$12.50	640	\$4,480	\$5,760				6,048 140	\$42,336 \$1,540	\$54,432 \$1,750	80 1,000	\$11,000	\$12,500
SPN 01: Spandrel repair	II If	\$150.00	\$12.50							20	\$3,000	\$3,600	1,000	\$11,000	\$12,500
of Not. Spandrer repair	- 11	\$150.00	\$180.00							20	\$3,000	\$3,000			
Subtotal					\$183,700	\$250,535		\$45,440	\$54,528		\$269,236	\$353,177		\$249,875	\$333,033
Overhead Profit	*	10%	25%		\$18,370	\$62,634		\$4,544	\$13,632		\$26,924	\$88,294		\$24,988	\$83,258
Performance Bond	*	3%	5%		\$6,062	\$15,658		\$1,500	\$3,408		\$8,885	\$22,074		\$8,246	\$20,815
Total Priorities (Façade Repairs)					\$208,132	\$328,827		\$51,484	\$71,567		\$305,044	\$463,545		\$283,108	\$437,105
* existing sealant is presumed as nonasheetos							Total Priority 1	"			·		-		•

^{*} existing sealant is presumed as nonasbestos Total Priority 1 \$259,616 \$400,395

ROOF REPAIRS														
ROF 01 - ROF 05: Roof Replacement (includes removal of existing roofing system down to concrete deck, repair of substrate, installation of 2 ply SBS modified bitumen system including vapor barrier, installation of in-wall type perimeter counterflashing, installation of pitch pockets and flashing at all roof penetrations.	sf	\$20.00	\$25.00				43,500	\$870,000	\$1,087,500					
Grand Total (Façade (all priorities) and Roof Repairs)								\$1,717,768	\$2,388,545					